


## Steps for calibrating touch screen display


### Calibrate the touch screen display



Mode **9-96** No **0** for calibration

1. Black "+" sign will appear on four corners of touch screen panel.
2. Tap "+" sign on the top left corner and it will change to red.
3. Tap "+" sign and slowly move in order from top left, top right, bottom left and bottom right. The color of "+" sign will change into red color. It indicates that calibration setup is completed.
4. Turn coin return lever and it will return to main screen.

### Check calibration of touch screen display



Mode **9-96** No **1** for checking calibration

1. Tap any spot on touch screen and "+" sign will appear at spot that was previously touched. It will end procedure of checking calibration.
2. Turn coin return lever and it will return to main screen.

# Steps for calibrating touch screen display

Procedure for calibrate touch screen display and check the calibration



**1** モード Press Mode



**2** アップ (ダウン ) Press UP & DOWN



**3** 書込み Press Confirmation It is necessary to input item number after confirm mode number 9



**4** アップ (ダウン ) Press UP & DOWN



**5** 書込み Press Confirmation



**6** アップ (ダウン ) Press UP & DOWN



**7** 書込み Press Confirmation



**8** 終了 Press End



: blinking